

Index

Run. No.	Document	Page	Product	Changes	Change time
2024-04-16	Catalog, Pricelist	2/24	Tooth plate S	Part no. got replaced: 0818102 -> 081810202	directly
	Catalog, Pricelist	2/24	Tooth plate S Zink-Nickel	Part no. got replaced: 0818101/zn -> 081810102/zn 0818102/zn -> 081810202/zn	directly
	Catalog, Pricelist	2/42	Rooftop holder Big Foot	Part no. got replaced: 08197610 -> 08197609 Now with the pad glued on	directly
	Catalog, Pricelist	4/4	Sliding element radial-axial	Part no. got replaced: 0779971 -> 077997101 0779972 -> 077997201	directly
	Catalog, Pricelist	8/7 - 8/9	SIGNUM Productprogramm	New product	directly
	Catalog, Pricelist	13/9	U-bolt	Part no. got replaced: 0506089 -> 050608901 the new one is 5 mm longer	directly
	Catalog, Pricelist	14/17	CENTUM® wall angle	New product	directly
2024-01-03	Catalog, Pricelist	2/24	Tooth plate S	Part no. got replaced: 0818101 -> 081810102	directly
	Catalog, Pricelist	2/42	Rooftop holder Big Foot 305	Part no. got replaced: 08197600 -> 08197606 Now with the pad glued on	directly
	Catalog, Pricelist	2/42	Rubber wedge Big Foot 450	Part no. got replaced: 08197616 -> 08197617 The inclination changes from 4° to 2.5°	directly
	Catalog, Pricelist	2/43	Joint adapter for Big FOOT® 305	new product	directly
	Catalog, Pricelist	4/4	Sliding element radial-axial	Part no. got replaced: 0779973 -> 077997301	directly
	Catalog, Pricelist	8/18	Duct sealing tape	New product, part no. 725111206	directly
	Catalog, Pricelist	13/27	Base plates	Part no. 0598701 and 0599701 will be deleted from the program	directly
	Catalog, Pricelist	13/31	Allen head cap screw	Change in packing for part no. 3445220 and 3445201	directly
	Catalog, Pricelist	14/5	T-lock plus	new product	directly
	Catalog, Pricelist	14/6	T-lock head	Renaming in T-lock	directly
	Catalog, Pricelist	1/23	U-bolt	Part-No. got replaced: 0507028 -> 050702801 the new one is 5 mm longer	directly
2023-09-13	Catalog, Pricelist	2/48	Joint holder with base plate	Will be replaced by joint holder with plate v/h	directly
	Catalog	3c/2	Spring insulator FH 2	Loadrange increased to 9545 N	directly
	Catalog	5/6	Pendular bolt joint M10/M10	New length and new wrench size	after sale
	Catalog, Pricelist	5/18	Hexagon-woodscrew	New product	directly
	Catalog, Pricelist	7/3	Brass expansion anchor	Part-No. 2060035 will be deleted from the programm	directly
	Catalog	7/6	Bolt anchor	The dowels with size 8 also have a seismic certificate	directly

Index

Run. No.	Document	Page	Product	Changes	Change time
	Catalog, Pricelist	1/7 - 1/8	Omnia MB	Clamping range 84 - 89 mm changed in 84 - 90 mm	directly
2023-04-01	Catalog, Pricelist	1/22	U-bolt	Part-No. got replaced: 0507022 -> 050702201 the new one is 5 mm longer	directly
	Catalog, Pricelist	2/3, 2/20, 2/21	C-profile rails	Change of the packaging unit	from 01.04.2023
	Catalog, Pricelist	2/49	Joint holder	Part-No. 08120600 and 08121100 got replaced by 08120601	after sale
	Catalog, Pricelist	2/49	Joint holder with terminal hole	Partl-No. got replaced: 0812072 -> 081207201	after sale
	Catalog, Pricelist	4/4	Spline end	will be deleted from the program	directly
	Catalog, Pricelist	4/11	Suspended bracket	Part-No. 07709902 got replaced by 07709903	directly
	Catalog, Pricelist	5/8	Distance angle	Change of the packaging unit	directly
	Katalog, Preisliste	5/11	Threaded coupling	Part-No. got replaced: 0700084 -> 0700085 0700104 -> 0700105	directly
	Catalog, Pricelist	5/17	Bolt screw	will be deleted from the program	directly
	Catalog, Pricelist	5/18	Wood screw with washer	Part-No. 3500012 got replaced by 350001218	directly
	Catalog, Pricelist	8/16	C-profile lining	Section for Stex 35 new in catalogue	directly
	Catalog, Pricelist	13/23	Clamping bow	Change of the packaging unit	directly
	Catalog, Pricelist	13/27	Base plate	Change in dimensions of Type III	directly
	Catalog, Pricelist	13/30	Double nipples	will be deleted from the program	directly
	Catalog, Pricelist	14/16	CENTUM angle coupler	will be deleted from the program	directly
	Catalog, Pricelist	14/25	CENTUM protecting cap	Our protecting caps for XL 80 have a new design and a new Part-No.	directly
	Catalog, Pricelist	1/23	U-Bolt	Part-Numbers will be replaced: 0507035 -> 050703501 0507042 -> 050704201 0507048 -> 050704801 0507140 -> 050714001 those are 5 mm longer	directly
2022-07-01	Catalog, Pricelist	7/4 - 7/5	Concrete screw R-LX	will be deleted from the program	directly
	Catalog, Pricelist	7/4 - 7/5	Concrete screw TSM	will be deleted from the program	directly
	Catalog, Pricelist	12/5	Sprinkler pipe clamp "SP"	Dimension 324 is new	directly
	Catalog, Pricelist	13/25	Slider GL 100	Change of material to V4A. The values of the loads have been adjusted	directly
	Catalog, Pricelist	14/9	Roof top holder XL 80	New Product	directly

Index

Run. No.	Document	Page	Product	Changes	Change time
	Catalog, Pricelist	1/23	U-Bolt	Part-No. 0507114 / 0507168 will be replaced by 050711401 / 050716801 - those are 5 mm longer	directly
2021-12-14	Catalog, Pricelist	1/24	Pipe clamp Clipstar	Dimension 28 will be deleted from the program	directly
	Catalog, Pricelist	2/40	Sound-decoupling set v/h holder 45	New product	directly
	Catalog, Pricelist	3a/11	Sound-decoupling set K	Part-no. 077034002 (new for tension loads) replaces part-no. 077034001	after purchase
	Catalog, Pricelist	3a/12	Fixpoint type FGL	Part-no.. 999770001 (new for tension loads) replaces part-no. 9997700	after purchase
	Catalog, Pricelist	5/11	Threaded coupling with inspection slot	will be deleted from the program	directly
	Catalog, Pricelist	7/4	Concrete screw R-LX	Seismic note	directly
	Catalog, Pricelist	8/9 - 8/10	Wire rope L-Fix	Extension by the variants trapeze hook, connector axial and tangential	directly
	Catalog, Pricelist	13/16	Corner plate	V2A will be deleted from the program, a new version with elongated holes in V4A	directly
	Catalog, Pricelist	13/17	Angle 40/5	3-hole and 4-hole new version with elongated holes	directly
	Catalog, Pricelist	13/19	Holder 45	new version with elongated holes	directly
	Catalog, Pricelist	13/32	Hexagon screw	M8x20 in V4A will be deleted from the program	directly
	Catalog, Pricelist, HD+IA-Catalog	Catalog 14/20, HD+IA 2/2	CENTUM® Z-guides	new version replaces both old versions, clamping thickness 16 mm	after purchase
	Catalog, Pricelist, HD+IA-Catalog	Catalog 14/20, HD+IA 2/2	CENTUM® Sliding stripe	will be replaced with new version. According to new Z-guide.	after purchase
	Catalog, Pricelist, HD+IA-Catalog	Catalog 14/21, HD+IA 2/3	CENTUM® Z-guide Set with U-bolt	new versions for XL120	directly
	Catalog, Pricelist	Catalog 14/24, HD+IA 1/5	CENTUM® Protecting cap	new look and new part-no. of our protecting caps.	directly
	Catalog, Pricelist, HD+IA-Catalog	Catalog 14/40, HD+IA 1/40	CENTUM® Square profile Load values	new loads for XL 200 because of a new steel grade	directly
	HD+IA-Catalog	1/12	CENTUM® connecting plate	new product	directly
	HD+IA-Catalog	1/30	CENTUM® girder clamping	new part-no.	directly

Index

Run. No.	Document	Page	Product	Changes	Change time
	HD+IA-Catalog	1/39	CENTUM® Wall- and roof bushing. Variable version now with Holder connection instead of rail section	New versions with new part-no.	directly
	HD+IA-Catalog	2/5	CENTUM® Sliding base, standing	Version for XL80	directly
	HD+IA-Catalog	2/6	Guide rail for sliding sledge, hanging	new product	directly
	HD+IA-Catalog	2/7 - 2/14	Sliding support	New versions with new part-no.	directly
	HD+IA-Catalog	2/15-2/22	Sliding sledge	New versions with new part-no.	directly
	HD+IA-Catalog	2/23	Sliding support as fixpoint	new product	directly
	HD+IA-Catalog	3/13	Locking lip adaptor	will be deleted from the program of the heavy-duty and industrial application catalog	directly
	HD+IA-Catalog	4/13	Hexagon screw	2 new dimensions	directly
		1/23	U-bolt	Part-No. 0507060 and 0507076 will be deleted from the program. Replacement: 050706001 and 050707601. Overall height now 5mm longer	directly
2021-08-17		2/50	Carrier console 36/40	will be replaced with carrier console 45/45	directly
		2/41	Rooftop holder BigFoot wedge	The wedges 2,5° and 5° will be replaced with wedge 4°	directly
		7/4	Concrete screw R-LX	The concrete screws with sleeve M8 and M10 will be replaced with a concrete screw with sleeve M8/M10	directly
		8/9	Wire rope L-Fix Toggle	New product	directly
		13/18	Knot triangle	Part-No. 0481407 and 0480407 will be replaced with 048140701 and 048040701. The distances between the holes now correspond to the steel versions	directly
		14/4	CENTUM profile	Loads of the CENTUM Profile XL200 have been adapted to the yield strength S235	directly
		14/18	CENTUM Thread connector XL 80	New load values	directly
		14/7	CENTUM Connector	Part-No. 164005010 and 1640805010 will be replaced with 1640005011. CENTUM Connector can now be used universally for all CENTUM profiles	directly